MATERIAL SAFETY DATA SHEET

Product Identification: Clearco STO-50 Silicone Transformer Oil

CLEARCO PRODUCTS CO., INC Emergency Telephone Number 3430-G PROGRESS DR CHEM-TEL: 1 (800) 255 3924

BENSALEM, PA 19020

Telephone: 1 (800) 533 5823 Date Prepared: 01/10/04 nc

SECTION II HAZARDOUS INGREDIENTS/IDENTITY INFORMATION – None Found

INGREDIENT DESCRIPTION	%	CAS	ACGIH	TLV	ACGIH	STEL	OSHA	PEL	SARA
	Weight	Number	PPM	MG/M3	PPM	MG/M3	PPM	MG/M3	313
Polydimethylsiloxane	80-99	63148-62-9	N/E	N/E	N/E	N/E	N/E	N/E	N/E

HMIS RATING

FLAMMABILITY 0 REACTIVITY 0 HEALTH 0 0- Minimal

SECTION III PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point >400°F / 200°C

Specific Gravity (H2O=1) .953

Vapor Pressure (20°C) Negl. MM HG

Vapor Density (Air = 1):

Evaporation Rate (EE=1)

Melting Point

Solubility In Water (20°C)

Solubility in Organic Solvent

Negl.

Negl.

Negl.

Insoluble

Soluble in Toluene

Appearance & Odor: Clear colorless liquid - Odorless

SECTION IV FIRE AND EXPLOSION HAZARD DATA

Flash Point: (Method Used) >400°F / 204°C by PMCC Flammable Limits: LEL: No Data UEL: No Data

Extinguishing Media: All standard firefighting media Special Fire Fighting Procedures: None Known

SECTION V - **REACTIVITY DATA**

Stability: Stable
Conditions to Avoid: None
Hazard Polymerization: Will Not Occur
Incompatibilities: None Known

SECTION VI HEALTH HAZARD DATA

Acute Signs/Effects of Overexposure:

Eye Contact: May cause Mild Eye Irritation.

Skin Contact:

Inhalation:

None Known.

Ingestion:

Medical Conditions Aggravated:

Other:

None Known

None Known

None Known

None Known

None Known

None Known

Chronic Effects of Overexposure:

None Known

Emergency and First Aid Procedures:

Ingestion None Known

Skin Wash with soap and water

Inhalation None Known

Eyes In case of contact, immediately flush eyes with plenty of water for at least 15 minutes and get medical

attention if irritation persists.

This product or one of its ingredients present 0.1% or more is not listed as a carcinogen or suspected carcinogen by NTP, IARC, or OSHA.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Spill Response: Wipe, scrape or soak up in an inert material and put in a container for disposal. Wash walking surfaces with detergent and water to reduce slipping hazard.

Disposal Method: Disposal should be made in accordance with Federal, State and Local regulations. Incineration recommended in approved incinerator according to Federal, State, and Local regulations..

SECTION VIII - PROTECTION AND PRECAUTIONS

Ventilation: None Known
Respiratory Protection: None Known
Eye and Face Protection: Safety Glasses

Protective Gloves: None Known

Other Protective Equipment: None Known

Precautions to be Taken in Handling and Storage: None Known Engineering Controls: None Known

SECTION IX - DEPARTMENT OF TRANSPORTATION DATA

DOT Proper Shipping Name : None
DOT Hazard Class: None
DOT Labels: None
UN/NA Number: None
Placards: None
Export: None

EPA Hazard Waste: None

Sara Hazard Class:

WHMIS Hazard Class: No Known WHMIS Class

CPSC Classification None
Transportation Class: None
RID (OCTI): None
ADR (ECE): None
RAR (IATA): None

DISCLAIMER

Information presented herein has been compiled from information provided to us by our suppliers and other sources considered to be dependable and is accurate and reliable to the best of our knowledge and belief but is not guaranteed to be so. We make no warranty as to the results to be obtained in using any material and since conditions of use are not under our control, we must necessarily disclaim all liability with respect to the use of any material supplied by us.